



Date: July 9, 2019

Building: Building #058 California Well Sample Repository

Inspected by: Jennifer Jackson

Topics: Earthquake Damage Assessment

On July 9, 2019 at approximately 0805 Paula Bray, Director of Facilities Operations, informed me that the California Well Sample Repository building needed to be assessed for earthquake bracing. I met with Facilities Management to conduct a walk-through of building #058. The building located behind the main entrance was inspected for earthquake damage. Items were not touched during the inspection. I was not able to complete the damage assessment as it was not safe to walk inside the building.

The building located in the back connected to Building 058 is not recommended for employees, students, or volunteers to work inside. Further damage assessment is required prior to employees, volunteers or students entering the building.



North end of the building was pushed out





**SAFETY &
RISK MANAGEMENT**

Jennifer Jackson
Business Continuity/Safety Specialist
California State University Bakersfield
Safety & Risk Management





**SAFETY &
RISK MANAGEMENT**

Jennifer Jackson
Business Continuity/Safety Specialist
California State University Bakersfield
Safety & Risk Management



Earthquake bracing is not secured



Earthquake bracing is not secured



**SAFETY &
RISK MANAGEMENT**

Jennifer Jackson
Business Continuity/Safety Specialist
California State University Bakersfield
Safety & Risk Management



Shelf is damaged

Jennifer Jackson, Business Continuity/Safety Specialist



**SAFETY &
RISK MANAGEMENT**

Jennifer Jackson
Business Continuity/Safety Specialist
California State University Bakersfield
Safety & Risk Management